Change Dallas to RS232 Interface

W Version:	Interface Connect Device
atus Setting	
IButton PreAmble Enable	Code
PostAmble Enable	NULL *
Remove Data Enable	NULL +
ID Code Auto Report Output Buzzer Enable	start Output length KB Country USA FW Update
hange Interface	Get Status Set Status

Launch the iButton utility. Select USB-KB and click on Connect Device:

Click on « to Serial » in the bottom left.

W Version: 1BT2-		terface USB KB Serial Port OM6	Connect	Connect Device	
atus Setting					
Button PreAmble Enable				ASCII	Code
11111					NULL -
PostAmble Enable					
20					NULL -
🗸 Remove Data Enable					
11111 .					NULL -
ID Code Auto Report	Output start	Output length	KB Country		
Buzzer Enable	0	8	USA	•	FW Update
to Serial				Set Status	Set Status



The utility will close and Windows will detect a new device.

If Aures install the Windows (Windows 7 PRO or PosReady 7), you will have a new COM port called Nuvoton in the Device manager.

Communications Port (COM6)
Communications Port (COM6)
Nuvoton Virtual Com Port (COM8)
Printer Port (LPT1)

If you are using Windows 10, you don't need a driver and you will have a new COM port called USB Serial Device.

On a new Windows 7 installation you will need the driver; you can find it on the AURES website <u>www.aures-support.com</u>.

